

Golfer Profile

Bag Focus	Primary Miss	Score Bracket	Equipment Age
Driver & Woods	Slice (Curves Right)	80s (Mid-Handicap)	5 – 10 Years Old
Target Lie Angle	Target Shaft Flex	Target Shaft Weight	Grip Core Sizing
1.0° Upright	Stiff (S) Mid-Launch	65g – 75g	Standard + 1 Wrap

Audit Diagnosis

Your divot pattern indicates the outside edge is digging in early, popping the face open at impact. An upright lie adjustment (**1.0° Upright**) is required to restore center-face contact. Playing 5–10 years old gear with a shaft that feels stiff like a board prevents proper energy loading at the top. Moving to a lighter shaft weight (**65g – 75g**) will allow your hands to release naturally & gain carry distance. Because your current driver setup is 5–10 years old, modern high-MOI weighting & multi-material face geometry will immediately reduce spin loss on off-center strikes.

You cannot out-practice a lie angle mismatch. When a club sole is 1.0° too flat, the toe catches turf milliseconds before ball strike, physically twisting the face open. The slice you are experiencing is an equipment symptom, not a mechanical flaw.

- To eliminate your slice, two variables must be synchronized:
- Dynamic Lie Angle:** Adjusted 1.0° upright so the sole glides level through turf.
 - Shaft EI Frequency:** Calibrating shaft weight to 65g – 75g so the clubhead squares effortlessly at impact without flipping your hands.

The 3 Critical Blindspots Costing You Strokes

Blindspot #1

The Swing Compensation Trap

Trying to swing "in-to-out" to fix a slice caused by flat lie geometry leads to nasty two-way hooks and lost compression.

Blindspot #2

The Stiff Shaft Myth

Playing an off-the-rack shaft that feels "stiff like a board" prevents proper kinetic loading, killing 18+ yards of carry.

Blindspot #3

10-Year MOI Spin Decay

Older clubheads produce 450+ RPM excess sidespin on toe strikes compared to modern multi-material tungsten weighting.

Your 3-Step Action Roadmap

Step 1

Save Your Specs

Keep this diagnostic report on your mobile phone or print a hard copy for your fitting session.

Step 2

Choose Studio

Select one of your matched certified studios below and schedule an in-person evaluation.

Step 3

Apply Voucher

Show code **BGF-50** upon arrival to apply your \$50 credit directly toward your session fee.

 **Official \$50 Studio Fitting Credit Certificate**

This certificate entitles **Nick Graff** to a \$50 credit toward an in-person fitting session at any certified studio partner. Mention code **BGF-50** when scheduling your bay time.

Voucher Code

BGF-50

Matched Certified Studios (Scottsdale, AZ)

 **Pete's Golf Studio • ★ 5.0 (48 Reviews)**

 1200 E Camelback Rd, Scottsdale, AZ

 Tech: TrackMan 4 Bay • Master AGCP Clubmaker

 **(480) 555-0123** (Accepts Voucher: BGF-50)

 **Scottsdale Custom Clubs • ★ 4.9 (34 Reviews)**

 8900 E Shea Blvd, Scottsdale, AZ

 Tech: Foresight GCQuad Studio • Outdoor Turf Access

 **(480) 555-0199** (Accepts Voucher: BGF-50)

Prefer to order custom clubs online? You can configure custom clubs built to these exact specs via our official partner **2nd Swing Golf** with doorstep delivery & a 30-day play guarantee.